

Ref #	Hits	Search Query	DBs	Default Operator	Plurals	Time Stamp
L1	1319	((draw adj work) or drawwork) and (drill\$3 or wellbore or borehole)	US-PGPUB; USPAT; EPO; DERWENT	OR	ON	2005/02/01 11:11
L2	0	1 and (flow near3 sens\$3) and tracer	US-PGPUB; USPAT; EPO; DERWENT	OR	ON	2005/02/01 11:12
L3	23	1 and (flow near3 sens\$3) and ((pressure or acoustic) near2 pulse)	US-PGPUB; USPAT; EPO; DERWENT	OR	ON	2005/02/01 11:43
L4	18	vibration and motor and (wong-albert-k.xa.)	US-PGPUB; USPAT; EPO; DERWENT	OR	ON	2005/02/01 11:47
L5	5	vibration and motor and (wong-albert-k.xp.)	US-PGPUB; USPAT; EPO; DERWENT	OR	ON	2005/02/01 11:49
L6	10376	((motor or pump) near3 (generat\$3 near3 signal)) and (vibrat\$3 or acoustic or pulse\$1)	US-PGPUB; USPAT; EPO; DERWENT	OR	ON	2005/02/01 11:51
L7	408	6 and (wellbore or drill\$3 or borehole)	US-PGPUB; USPAT; EPO; DERWENT	OR	ON	2005/02/01 11:53
L8	306	7 and transmi\$5	US-PGPUB; USPAT; EPO; DERWENT	OR	ON	2005/02/01 11:55
L9	6	8 and ((rotat\$5 near3 rate) and wob)	US-PGPUB; USPAT; EPO; DERWENT	OR	ON	2005/02/01 11:56